



RECEIVED

13 AUG 14 PM 1:53

SUPERFUND DIV.  
DIRECTOR'S OFC.

## Delek Logistics Operating, LLC

1001 SCHOOL STREET  
EL DORADO, ARKANSAS 71730  
(870) 862-8111

VIA CERTIFIED MAIL

August 12, 2013

Mr. Nelson Smith  
Superfund Division (6SF-PC)  
U. S. EPA Region 6  
1445 Ross Avenue  
Dallas, TX 75202-2733

RE: *Clean Water Act, Section 308 Information Request - Response*  
*Oil Spill in Columbia County, Arkansas on March 09, 2013*  
**NRC Report No: 104525**

Dear Mr. Smith:

In a letter dated July 12, 2013 additional information was requested regarding the event in Columbia County, Arkansas on March 09, 2013. Please find the responses below and the attached final report related to the event.

1. A report regarding the spill of crude oil into a water body, which occurred on or about March 09, 2013. (If the name of the water body is not available, use the best description available). **(See included report)**
2. The amount of product spilled (in either barrels or gallons). For release of mixtures, included the total volume and either volumes or relative percentages of each component. If any reported value is an estimate, describe the method used to develop the estimate. **(See page 21 of the included report and Attachment N)**
3. Duration of the spill event. Report the time and date the spill began, how long the product remained in the watercourse, as well as on the shoreline or banks and when the cleanup operations were considered complete and all product removed from waters of the United States and adjoining shoreline. **(See page 4 of the included report)**
4. The cause of the spill. **(See page 4 of the included report)**
5. Name of the immediate receiving ditch, creek, stream, river, lake, arroyo, swale, ect. if known. **(See Section 3 of the included report)**

- a. Also include the names of all downstream receiving waters that the spill affected
  - b. Additionally, list all downstream receiving water bodies to the first major river or lake, regardless of whether or not the spill affected the water bodies.
6. Site location map. **(See Attachment B of the included report)**
7. Drawing of the showing locations of the facilities. **(See Attachment B of the included report)**
8. Sketch of the spill site showing extent of the spill. **(See Attachment B of the included report)**
9. Photographs of the spill and the spill site both before and after cleanup. **(See Attachment M of the included report)**
10. Documentation of any penalties assessed by local, state or federal agencies. **(No penalties have been assessed at this time)**
11. State the owner and operator of the equipment or facility from which the spill originated. **(The site is owned by SALA Gathering Systems, LLC and operated by Delek Logistics Operating, LLC)**

I am providing in the enclosed CDs with the final report and supporting documents.

Please contact me at (870) 864-1257 or [scott.wiggins@delekrefining.com](mailto:scott.wiggins@delekrefining.com) if you have any questions regarding this submittal.

Sincerely,



James Scott Wiggins  
EHS Manager  
Delek Logistics Operating, LLC

enclosed

cc: John Warren  
Mike Norman  
George Garten  
Glenn Green  
File

---